## Oxygen

Multi-layer, flexible PVC hose, reinforced with polyester mesh. Specifically for conducting oxygen in welding equipment.



## **Features**

- For industrial use.
- Highly flexible and easy to handle.
- Highly resistant to breakage when extended.
- Highly resistant to traction (7.5 MPa) and pressure at high temperatures.
- Good chemical resistance associated with PVC's resistance chart.
- Recommended temperature for use between -10°C and 60°C.
- · Rubber option.









EASY TO USE







## **Applications**

Conducting oxygen and acetylene for welding.

INT ø mm	INT ø in	EXT ø mm	WEIGHT g/m	OPERATING PRESSURE bar	MINIMUM BURST PRESSURE bar
8	5/16"	15	160	20	60
10	³/e"	17	170	20	60





210